13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	P.	Date of payment

Log Book:-

works Commencement Date 18/11/2022

Name of work:- maintenance of Existing borewells at village areas in choodeshwari wards 02 of yelahanka Sub division.

Agency:- Sri Sadiyan (Ganesh Engineering works)

Estimate Cost:- 30.00 Lakhs

Job number:- 002-23-000013

REGISTER OF ATTENDANCE & FEES

Name of the Institute

FOR THE MONTH OF APRIL 2023

Section Place

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No of days present	FEES Rs.	P	Date of payment

REGISTER OF ATTENDANCE & FEES

Name of the Institute

FOR THE MONTH OF APRIL 2023

Section Place

(3)

Sl. No	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No of days present	FEES Rs.	P.	Date of Payment
14		Lower Housing													-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	2 NO		✓	
15		Carbon bushing, Thrust bearing bleeder body													-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	2 NO		✓	
16		oil Seal													-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1 NO		✓	
17		oil Seal steel bush													-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	1 NO		✓	
18		Guide vane													-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1 NO		✓	
19		Impeller shell moulded with bottom bronze.													-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1 NO		✓	
20		Discharge outlet													-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1 NO		✓	
21		steel bush													-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1 NO		✓	
22		pump shaft													-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1 NO		✓	
23		Non return valve													-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1 NO		✓	
24		Cable Guard													-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1 NO		✓	
25		Inlet filter													-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1 NO		✓	
26		Reconection charges of pumping.													-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1 NO		✓	

Remarks

Asst. Executive Engineer

REGISTER OF ATTENDANCE & FEES

Name of the Institute

FOR THE MONTH OF MAY 2023

Section Place

Sl. No	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No of days present	FEES Rs.	P.	Date of payment
								Sri Kondareddi prasanth kyasth										Sri Sreedevanahalli shiva Hara sai shanthikshetra												Sri Hanchahalli Ranna Hanuman Temple											
6	Transportation of puppy material	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	3 NO	✓		
7	Labour charges (over loading)	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	3 NO	✓		
8	Repairs to motor	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	3 NO	✓		
9	Replacement of motor parts	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3 NO	✓		
10	Rotor	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3 NO	✓		
11	upper flange	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO	✓		
12	Lower flange	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO	✓		
13	upper Housing	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	3 NO	✓		

Number Present M
Daily C

Number M
C

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF MAY 2023

Name of the Institute Section Place

(5)

Sl No	Admission No	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No of days present	FEES Rs.	P	Date of payment
14		Lower Housing.	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	3 NO			
15		Carbon housing, thrust bearing blocks - assembly	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	3 NO			
16		oil Seals	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	4 NO			
17		oil Seal Steel bush.	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	4 NO			
18		Guide vane	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	4 NO			
19		Impeller Shaft welded with the lower bush	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	4 NO			
20		Discharge outlet	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	4 NO			
21		Steel bush	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	4 NO			
22		pump shaft	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 NO			
23		non return valve	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	2 NO			
24		Cable Guard	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	3 NO			
25		Strainer filter	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	3 NO			
26		Rectification charges of pumping	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	3 NO			

Number present M
Daily F
Private M

Ramesh Jadhav
Asst Executive Engineer
Yelahanka Sub Division
Bangalore

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF JUNE 2023

Name of the Institute: Section: Place:

Sl No	Admission No	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No of days present	FEES Rs.	FEES P.	Date of payment
					3rd Household first Sabha								8th Household 5th Sabha									8th Hotahalli Ganapathi Temple									9th RD Akshaya Layout Innamkaral												
6	Transportation of pumping material	-	-	1	-	-	-	-	-	-	-	1	-		-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4 NO	✓		
7	Labour charges (over hauling)	-	-	1	-	-	-	-	-	-	-	1	-		-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4 NO	✓		
8	Repairs to motor	-	-	1	-	-	-	-	-	-	-	-	1		-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4 NO	✓		
9	Replacement of motor parts	-	-	-	1	-	-	-	-	-	-	-	1		-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4 NO	✓		
10	Rotar	-	-	-	1	-	-	-	-	-	-	-	-		1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	4 NO	✓		
11	upper flange	-	-	-	-	1	-	-	-	-	-	-	-		1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	4 NO	✓		
12	lower flange	-	-	-	-	1	-	-	-	-	-	-	-		1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	4 NO	✓		
13	upper Housing	-	-	-	-	1	-	-	-	-	-	-	-		1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	4 NO	✓		

Yelahanka, Bangalore

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF JUNE 2022

Name of the Institute ____ Section ____ Place ____

Sl No	Admission No	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No of days present	FEES Rs.	P.	Date of payment
14		Lower Housing.	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	4 NO			
15		Carbon housing. Thrust bearing with assembly	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	4 NO			
16		oil Seal	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	3 NO			
17		oil Seal Steel bush	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	3 NO			
18		Guide vane	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	3 NO			
19		impeller shell moulded with bronze lining	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	3 NO			
20		Discharge outlet	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	3 NO			
21		steel bush	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	3 NO			
22		pump shaft	1	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	4 NO			
23		Non return valve	1	-	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	4 NO			
24		Cable Guard	-	1	-	-	-	-	-	-	1	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	4 NO			
25		Drain tester	-	1	-	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	4 NO			
26		Recirculation channel pumping.	-	1	-	-	-	-	-	-	-	1	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	4 NO			

Number present M. ____
Days C ____
Absent M. ____

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF JULY 2023

(8)

Name of the Institute: Section: Place:

Sl. No	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs	FEES P	Date of payment
6	Transportation of pumping machinery		-	-	-	1	-	-	-	-	-	-	-	1		-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	4	00	✓	
7	Labour charges (over Heading)		-	-	-	1	-	-	-	-	-	-	-	1		-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	4	00	✓	
8	Repairs to motor		-	-	-	1	-	-	-	-	-	-	-	1		-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	4	00	✓	
9	Replacement of motor parts		-	-	-	-	1	-	-	-	-	-	-	1		-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	4	00	✓	
10	Rotor		-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	4	00	✓	
11	upper flange		-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	4	00	✓	
12	Lower flange		-	-	-	-	1	-	-	-	-	-	-	-	1		-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	4	00	✓	
13	upper Housing		-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	4	00	✓	

1st Kanchipuram Layout 14th Cross

1st Floor, Ashirwad Complex, Tank Bund Road, Near Bus Stand, Hanamkonda (Near Railway Station)

1st Floor, Ashirwad Complex, Tank Bund Road, Near Bus Stand, Hanamkonda (Near Railway Station)

Assistant Executive Engineer
Yellareddy Sub Division
(Rural Circle-II)
Yellareddy, Kamareddy

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF JULY 2023

(9)

Name of the Institute

Section Place

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Total days present	FEES Rs	P	Date of payment
14		Lower Housing	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	3 NO			
15		Carbon housing	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	3 NO			
16		oil Seal	1	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
17		oil Seal Steel bush	1	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
18		Guide vane	1	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
19		Impeller shell moulded with aluminium bronze	1	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
20		Suction outlet	-	1	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
21		steel bush	-	1	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
22		pump shaft	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
23		non return valve	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
24		Cable Guard	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
25		Brass filter	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			
26		Re erection charges of pumping	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	4 NO			

Painting

Removed

Number present M
Daily E

REGISTER OF ATTENDANCE & FEES

FOR THE MONTH OF August 2023

Name of the Institute

Section Place

(10)

Sl. No	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Total days present	FEES Rs.	P.	Date of payment
										4th September									15th November											16th November									
6		Transportation of pumping mechanics	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3 NO			✓
7		Labour charges (wet healing)	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3 NO			✓
8		Repairs to motors	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO			✓
9		Replacement of motor parts	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO			✓
10		Rotor	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO			✓
11		upper flange	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO			✓
12		Lower flange	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO			✓
13		upper Housing	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO			✓

Number present M
Daily E

Initials M
E

Yeshwanthpur, Bangalore

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF August 2023

Name of the Institute ____ Section ____ Place ____

Sl No	Admission No	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs	P	Date of payment
14		Lower Housing	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	4 no				
15		Carbon housing	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	4 no				
16		oil Seal	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	4 no				
17		oil Seal steel bush	-	1	-	-	-	-	-	-	-	-		1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	4 no				
18		Guide vane	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	1	4 no				
19		Impeller shell moulded with aluminium bronze	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				
20		Discharge outlet	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				
21		Steel bush	-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				
22		pump shaft	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				
23		Non return valve	-	-	-	-	1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				
24		Cable Guard	-	-	-	-	-	1	-	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				
25		Stuff tube	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				
26		Reduction sleeve of pumping	-	-	-	-	-	-	1	-	-	-	-	-	-	1	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	3 no				

Remarks

Asst. Executive Engineer

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF SEPTEMBER 2023

(12)

Name of the Institute _____ Section _____ Place _____

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs.	P.	Date of payment
						1st Narayanakhedi Lagan, 1st cross Road								1st Nayanakhedi, near Tank											1st Nayanakhedi, AP, 4th A Cross Road													
6	Transportation of pumping machines		-	-	-	-	-	-	-	-	-	-	-	1		-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	3 NO			✓
7	Labour charges (over hauling)		-	-	-	1	-	-	-	-	-	-	-	1		-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	3 NO			✓
8	Repairs to motors		-	-	-	1	-	-	-	-	-	-	-	-		1	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	3 NO			✓
9	Replacement of motor parts		-	-	-	-	1	-	-	-	-	-	-	-		1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	3 NO			✓
10	Rotor		-	-	-	-	1	-	-	-	-	-	-	-		1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	-	3 NO			✓
11	upper flange		-	-	-	-	-	1	-	-	-	-	-	-		1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	3 NO			✓
12	Lower flange		-	-	-	-	-	1	-	-	-	-	-	-		1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	3 NO			✓
13	upper housing		-	-	-	-	-	1	-	-	-	-	-	-		1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	-	-	3 NO			✓

Number present M
Daily E
Initials M

Asst. Executive Engineer

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF SEPTEMBER 2021

Name of the Institute

Section

Place

(13)

Sl. No.	Admission No.	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	Total Days present	FEES Rs	P.	Date of payment
14		Lower housing	-	-	-	-	-	-	1	-	-	-	-	-		-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3 NO			
15		Carbon housing	-	-	-	-	-	-	1	-	-	-	-	-		-	-	-	1	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3 NO			
16		oil seal	-	-	-	-	-	-	-	1	-	-	-	-		-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	-	3 NO			
17		oil seal steel bush	-	-	-	-	-	-	-	1	-	-	-	-		-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	-	3 NO			
18		Guide vane	-	-	-	-	-	-	-	1	-	-	-	-		-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	3 NO			
19		impeller shaft moulded	1	-	-	-	-	-	-	-	1	-	-	-		-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	4 NO			
20		Discharge outlet	1	-	-	-	-	-	-	-	-	1	-	-		-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	1	-	-	4 NO			
21		steel bush	1	-	-	-	-	-	-	-	-	1	-	-		-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	1	-	-	4 NO			
22		pump shaft	-	1	-	-	-	-	-	-	-	1	-	-		-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	4 NO			
23		non return valve	-	1	-	-	-	-	-	-	-	-	1	-		-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	1	-	-	4 NO			
24		Cable Guard	-	-	1	-	-	-	-	-	-	-	1	-		-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	3 NO			
25		Strainer fitter	-	-	1	-	-	-	-	-	-	-	1	-		-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	3 NO			
26		Re erection charges of pumping	-	-	1	-	-	-	-	-	-	-	1	-		-	-	-	-	-	-	1	-	-	-	-	-	-	-	-	-	-	-	-	-	3 NO			

Number present M
Daily fl

Initials M

Asst Executive Engineer
Name of the Office
Station
```
Maintenance, Tungabhadra
```

REGISTER OF ATTENDANCE & FEES FOR THE MONTH OF OCTOBER 2023

(14)

Name of the Institute ____ Section ____ Place ____

Sl. No	Admission No	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	No. of days present	FEES Rs	P	Date of payment
				20th Nagalu Legend 2nd time MC							21st Ariyan Hyundai HP 3rd Grading																											
6		Transportation of pumping mechanical	-	-	1	-	-	-	-	-	1	-	-	-		2x0	✓																					
7		Labour charges (over hauling)	-	-	1	-	-	-	-	-	1	-	-	-		2x0	✓																					
8		Repairs to motor	-	-	1	-	-	-	-	-	1	-	-	-		2x0	✓																					
9		Replacement of motor parts	-	-	-	1	-	-	-	-	1	-	-	-		2x0	✓																					
10		Rotor	-	-	-	1	-	-	-	-	1	-	-	-		2x0	✓																					
11		upper flange	-	-	-	1	-	-	-	-	1	-	-	-		2x0	✓																					
12		Lower flange	-	-	-	-	1	-	-	-	1	-	-	-		2x0	✓																					
13		upper housing	-	-	-	-	1	-	-	-	1	-	-	-		2x0	✓																					
											Receiving voucher No.																											
		No. of days present M. Daily E.																																			
		Initials M.																																			

OCTOBER-2027

REGISTER OF ATTENDANCE & FEES

Name of the Institute

Sl No	Admission No	NAMES	1	2	3	4	5	6	7	8	9	10	11	12	
14		Louver housing	-	-	-	-	1	-	-	-	-	1	-	-	= 2NO
15		Carbon housing	-	-	-	-	1	-	-	-	-	1	-	-	= 2NO
16		oil seal	-	-	-	-	-	1	-	-	-	1	-	-	= 2NO
17		oil seal steel bush	-	-	-	-	-	1	-	-	-	1	-	-	= 2NO
18		Guide vane	-	-	-	-	-	1	-	-	-	-	1	-	= 2NO
19		Impeller shell moulded	-	-	-	-	-	1	-	-	-	-	1	-	= 2NO
20		Discharge outlet	-	-	-	-	-	-	1	-	-	-	1	-	= 2NO
21		steel bush	-	-	-	-	-	-	1	-	-	-	1	-	= 2NO
22		pump shaft	-	-	-	-	-	-	1	-	-	-	1	-	= 2NO
23		non return valve	-	-	-	-	-	-	1	-	-	-	-	1	= 2NO
24		Cable Guard	1	-	-	-	-	-	-	1	-	-	-	1	= 3NO
25		Strainer filter	1	-	-	-	-	-	-	1	-	-	-	1	= 3NO
26		Recirculation closed pump	-	1	-	-	-	-	-	1	-	-	-	1	= 3NO

Number present-M
Daily E